



AREPAs reference list of marine and offshore tasks

Type	Year	Location	Damage	AREPA's effort
Crane ship	2017/2018	Rotterdam, The Netherlands	Oil/Grease	Restoration
Rig	2017	Tyra Field, offshore, Denmark	Oil	Advice and restoration
Container ship	2017	Rotterdam, Holland	Fire	Analyses and advice
Ferry	2017	Stockholm, Sweden	Fire	Analyses, advice, and restoration
Sail yacht	2017	Vollenhove, The Netherlands	Dust	Restoration
Crane vessel	2017	Singapore	Dust	Restoration
Storage/production vessel	2017	Schiedam, The Netherlands	Dust	Restoration
RWS inspection vessel	2017	Harlingen, The Netherlands	Dust	Restoration
Cutter suction dredger	2017	Rotterdam, The Netherlands	Dust	Restoration
Fishing cutter	2017	Hvide Sande, Denmark	Fire	Analyses and advice
Rig	2017	Tyra Field, offshore, Denmark	Water	Advice and restoration
High-speed ferry	2017	Aarhus, Denmark	Fire	Analyses, advice, and restoration
Military ship	2017	Frederikshavn, Denmark	Fire	Analyses and advice
Ferry	2017	Frederikshavn, Denmark	Fire	Analyses and advice concerning cleaning
Container ship	2016	Istanbul, Turkey	Fire	Analyses and advice concerning cleaning
Rig	2016	Dan Field, Denmark	Water	Advice and restoration
Container ship	2016	Salalah, Sultanate of Oman	Fire	Analyses and advice
Container ship	2016	Las Palmas, Gran Canaria, Spain	Fire	Analyses and advice
Standby safety vessel	2016	Esbjerg, Denmark	Fire	Advice and restoration
Mussel fishing vessel	2016	Jegindø, Denmark	Dust from extinguishing plant	Advice
Heavy load carrier	2016	Cadiz, Spain	Fire	Restoration
Pipe layer	2016	Kinderdijk, The Netherlands	Dust	Restoration
Dredger	2016	Djeddah, Saudi Arabia	Fire	Analyses and advice
Pipe layer	2016	Krimpen aan den IJssel, The Netherlands	Dust	Restoration
LNG tanker	2016	Rotterdam, The Netherlands	Oil	Restoration
Rig	2016	Dan Field, offshore, Denmark	Water	Advice and restoration
Rig	2016			Advice
Trawler	2016	Thyborøn, Denmark	Fire	Analyses and advice

Type	Year	Location	Damage	AREPA's effort
Icebreaker	2016	Luleå, Sweden	Fire	Analyses and advice
Cargo	2016	Stockholm, Sweden	Fire	Analyses and advice
Swedish Coast Guard	2016	Stockholm, Sweden	Fire	Analyses, advice, and restoration
Ferry	2016	Stockholm, Sweden	Fire	Analyses, advice, and restoration
Military ship	2016	Frederikshavn, Denmark	Water	Advice and restoration
Offshore supply ship	2016	Esbjerg, Denmark	Hydrochloric acid	Analyses, advice, and restoration
Offshore tugs/supply ships	2016	Fredericia, Denmark	Maintenance	Advice
Jack-up unit	2016	Offshore, Denmark	Rainwater	Advice and restoration
LNG carrier	2016	Dubai, UAE	Fire	Analyses and advice
Dept Flexlay vessel	2015	Rio de Janeiro, Brazil	Fire	Analyses and advice
Container ship	2015	Seattle, Washington, USA	Fire	Analyses and advice
Motor vessel	2015	Aalborg, Denmark	Fire	Analyses and advice
Crane vessel	2015	Rotterdam, The Netherlands	Corrosion	Restoration
Pipe burying vessel	2015	Schiedam, The Netherlands	Dust	Restoration
Construction vessel	2015	Schiedam, The Netherlands	Dust	Restoration
Passenger (cruise) Ship	2015	Marseille, France	Water	Restoration
Pipe layer	2015	Kinderdijk, The Netherlands	Dust	Restoration
Pipe layer	2015	Singapore	Dust	Restoration
Pipe layer	2015	Krimpen aan den IJssel, The Netherlands	Dust	Restoration
Dredging and offshore works	2015	Greenock, Scotland	Fire	Analyses and advice
Container ship	2015	Nansha, Guangzhou, China	Fire	Analyses and advice
Oil products tanker	2015	Setubal, Portugal	Fire	Analyses and advice
Trawler	2015	Tórshavn, Faroe Islands	Fire + salt water	Analyses and advice
Dept Flexlay vessel	2015	Brazil	Fire	Analyses and advice
Ferry	2015	Gdansk, Poland	Salt water	Advice and restoration
Ship	2015	Hellerup, Denmark	Fire	Analyses, advice, and restoration
Trawler	2015	Nuuk, Greenland	Fire	Analyses and advice
Trawler	2015	Nuuk, Greenland	Fire	Analyses and advice
Restaurant ship	2015	Søby Æro, Denmark	Fire	Analyses and advice
Fish-processing trawler	2015	Torshavn, Faroe Islands	Fire	Analyses and advice
Fishing vessel	2014	Nykøbing Mors, Denmark	Fire	Analyses, advice, and restoration
Sailing vessel	2014	Frederikshavn, Denmark	Fire	Analyses and advice
Supply ship	2014	Thyborøn, Denmark	Fire	Analyses, advice, and restoration
Fishing vessel	2014	Esbjerg, Denmark	Fire	Analyses and advice
Ferry	2014	Grenaa, Denmark	Water	Advice and restoration
Crane ship	2014	Rotterdam, The Netherlands	Oil/Grease	Restoration



Type	Year	Location	Damage	AREPA's effort
Supply vessel	2014	Schiedam, The Netherlands	Fire	Restoration
Hopper dredger	2014	Duinkerke, Belgium	Dust	Restoration
Hopper dredger	2014	Moerdijk, The Netherlands	Dust	Restoration
Container ship	2014	Urk, The Netherlands	Dust	Restoration
Drilling platform	2014	Munkebo, Denmark	Short-circuit	Analyses and advice
Supply ship	2014	Hvide Sande, Denmark	Fire	Analyses, advice, and reconditioning of parts
LNG vessel	2014	Fujairah, United Arab Emirates	Fire	Analyses and advice
Tug boat	2014	Kalundborg, Denmark	Fire	Analyses and advice
Ferry	2014	Hou, Denmark	Fire	Analyses and advice
Supply ship	2014	Singapore	Fire	Analyses and advice
Pumping station	2014	Horsens, Denmark	Fire	Analyses, advice, and restoration
Fishing vessel	2014	Torshavn, Faroe Islands	Collision and Freon	Analyses and advice
Drillship	2014	Geoje, Korea	Fire	Analyses and advice
Fishing vessel	2014	Thyborøn, Denmark	Fire	Analyses and advice
Drilling jack up	2014	Aberdeen, Scotland	Fire	Analyses and advice
Research ship	2013/2014	Ulsteinvik, Norway	Water	Analyses, advice, and restoration
Cargo ship	2013	Bergen, Norway	Fire	Analyses and advice
Carrier	2013	Frederiksværk, Denmark	Fire	Analyses, advice, and restoration
Gas carrier	2013	Pointe Noire, Congo	Dirt and salt	Advice
LNG tanker	2013	Fujairah, United Arab Emirates	Explosion in switchboard	Advice and restoration
Fishing vessel	2013	Thyborøn, Denmark	Fire	Analyses and advice
Coaster	2013	Skagen, Denmark	Fire	Analyses, advice, and restoration
Pipe burying vessel	2013	Belfast, Ireland	Dust	Restoration
Cable layer	2013	Shanghai	Dust/new built	Restoration
Cable layer	2013	Shanghai	Dust/new built	Restoration
LPG tanker	2013	Barbedos	Fire	Analyses and advice
Trawler	2013	Tórshavn, Faroe Islands	Fire	Analyses, advice, and restoration
Freight and passenger ferry	2013	Klaipeda, Lithuania	Fire	Analyses and advice
Offshore platform	2013	The North Sea	Water	Advice and restoration
Mobile offshore drilling unit	2013	Singapore	Water	Advice
Tanker	2013	Napoli, Italy	Brand	Analyses, advice, and restoration
Trawler	2012	Skagen, Denmark	Sand and dust	Restoration
Icebreaker	2012	Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Trawler	2012	Hafnarfjordur, Iceland	Fire	Analyses and advice
Supply ship	2012	Strendur, Faroe Islands	Soot	Analyses and advice



Type	Year	Location	Damage	AREPA's effort
LNG tanker	2012	Labuan, Malaysia	Salt water	Advice and restoration
Platform	2012	The North Sea	Cooling liquid	Advice and restoration
Supply ship	2012	Shekou, China	Dust	Advice
Platforms	2012	The North Sea	Water and fire	Advice and restoration
Ferry	2012	Esbjerg, Denmark	Fire	Advice and restoration
Tug	2012	Brazil	Fire	Analyses and advice
Inspection vessel	2012	Frederikshavn, Denmark	Fire	Advice
Roll-on/roll-off ferry	2012	Ijmuiden, Holland	Fire	Analyses, advice, and restoration
Roll-on/roll-off carrier	2011	Luxhaven, Germany	Fire	Analyses, advice, and restoration
Offshore platform	2011 + 2012	Offshore, Stavanger, Norway + Hirtshals, Denmark	Salt	Analyses and advice
Gas Tanker	2011	Colombo, Sri Lanka	Fire	Analyses and advice
Offshore platform	2011	Norway	Fire	Restoration
Research ship	2011	Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Ro/Ro	2011	Odense, Denmark	Fire	Analyses and advice
Motor yacht	2011	Nice, France	Fire	Analyses, advice, and restoration
Towing vessel	2011	Las Palmas, Gran Canaria	Fire	Analyses and advice
Seismologic research ship	2011	Odense, Denmark	Fire	Analyses, advice, and restoration
Tanker	2011	Antwerp, Belgium	Fire	Analyses and advice
Offshore platform	2011	Doha, Qatar	Fire	Analyses and advice
Supply vessel	2011	Frederikshavn, Denmark	Fire	Analyses and advice
Ferry	2011	Odense, Denmark	Fire	Analyses and advice
Frigate	2011	Odense, Denmark	Fire	Analyses and advice
Ferry	2011	Odense, Denmark	Fire	Analyses and advice
Ferry	2011	Frederikshavn, Denmark	Fire	Analyses and advice
Frigate	2011	Fredericia, Denmark	Dust	Restoration
Tanker	2011	Gran Canaria	Fire	Analyses, advice, and restoration
Royal yacht	2010	Frederikshavn, Denmark	Smoke	Analyses and advice
Ferry	2010	Copenhagen, Denmark	Fire	Analyses, advice, and restoration
Ferry	2010	Gdansk, Poland	Fire	Analyses and advice
Supply vessel	2010	Aberdeen, Scotland	Fire	Analyses and advice
LPG carrier	2010	China	Fire	Analyses and advice
Cargo ship	2010	Odense, Denmark	Fire	Analyses and advice
Trawler	2010	Falmouth, United Kingdom and Runavik, the Faroe Islands	Fire	Analyses, advice, and restoration
Passenger-cargo ship	2010	Odense, Denmark	Fire	Analyses and advice

Type	Year	Location	Damage	AREPA's effort
Frigate	2010	Odense, Denmark	Dust	Advice and restoration
Tanker	2010	Singapore	Fire	Analyses and advice
Carrier	2010	Esbjerg, Denmark	Fire	Restoration and advice
Ferry	2010	Ijmuiden, Holland	Fire	Analyses and advice
Container ship	2010	Bremerhaven, Germany	Fire	Analyses and advice
Seismographic research ship	2010	Dubai	Fire	Analyses and advice
Frigate	2010	Odense, Denmark	Dust	Advice and restoration
Cargo ship	2010	Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Motor yacht, Azimut 43S	2010	Brejning, Denmark	Powder	Advice and restoration
Jack up drilling platform	2010	Outside Alexandria, Egypt	Dust, grease, etc.	Analyses and advice
Shrimping trawler	2010	Hirtshals, Denmark	Fire	Analyses and advice
Fishing cutter	2010	Grenaa, Denmark	Fire	Advice
Trawler	2010	Skagen, Denmark	Salt water	Advice
Shrimping trawler	2010	Fredericia, Denmark	Fire	Analyses and advice
Ro/Ro	2009	Odense, Denmark	Fire	Analyses and advice
Frigate	2009	Odense, Denmark	Fire	Analyses and advice
Tug	2009	Quebec, Canada	Fire	Analyses, advice, and restoration
Production platform	2009	The North Sea	Salt in turbine panel	Restoration
Ferry	2009	Hov, Denmark	Fire	Analyses and advice
Ferry	2009	Bremerhaven, Germany	Fire	Analyses and advice
Jackuprig	2009	The North Sea	Dust	Restoration
Trawler	2009	Frederikshavn, Denmark	Fire	Analyses and advice
Drilling platform	2009	Silkeborg, Denmark		Decontamination of 46 PCBs
Ro/Ro	2009	Odense, Denmark	Fire	Analyses and advice
AH-Tug/Standby/Supply vessel	2009	Kristiansund, Norway	Fire	Analyses, advice, and restoration
Container ship	2009	Odense, Denmark	Fire	Analyses and advice
Trawler	2008	Runavik, Faroe Islands	Fire	Analyses and advice
Anchor handling tug support vessel	2008	Brazil	Fire	Analyses and advice
Carrier	2008	Ferrol, Spain	Dust	Restoration
Ferry	2008	Fredericia, Denmark	Fire	Analyses, advice, and restoration
Backhoe hopper dredger	2008	Løgstør, Denmark	Fire	Analyses and advice
Cargo ship	2008	Aarhus, Denmark	Fire	Analyses and advice
Tanker	2008	Las Palmas, Gran Canaria	Fire	Analyses and advice
Feeder	2008	Dakar, Senegal	Fire	Analyses and advice

Type	Year	Location	Damage	AREPA's effort
Cargo ship	2008	Gothenburg, Sweden	Fire	Analyses, advice, and restoration
Carrier	2008	Fene, Spain	Dust	Restoration
Container ship	2008	Odense, Denmark	Fire	Analyses and advice
Tanker	2008	Gothenburg, Sweden	Fire	Analyses, advice, and restoration
Platform	2008	Silkeborg, Denmark	Fire	Analyses and advice
Dry cargo vessel	2008	Dakar, Senegal	Fire	Analyses and advice
Container carrier	2007	Adelaide, Australia	Fire	Analyses and advice
Tanker	2007	Skagen, Denmark	Fire	Analyses, advice, and restoration
Tanker	2007	Istanbul, Turkey	Fire	Analyses and advice
Surveying vessel	2007	Thyborøn and Silkeborg, Denmark	Extinguishants	Analyses, advice, and restoration
Liner	2007	Aalborg, Denmark	Salt water	Advice and restoration
Ferry	2007	Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Ferry	2007	Helsingborg, Sweden	Fire	Analyses, advice, and restoration
Ferry	2007	Frederikshavn, Denmark	Fire	Analyses and advice
Collier	2007	Skødstrup, Denmark	Water	Restoration
Trawler	2007	Penco, Chile	Fire	Analyses and advice
Hopper dredger	2007	Fredericia, Denmark	Fire	Analyses and advice
Diver vessel	2007	Stavanger, Norway	Fire	Analyses and advice
Trawler	2007	Hirtshals, Denmark	Fire	Analyses and advice
Trawler	2007	Penco, Chile	Fire	Analyses and advice
Dredger	2007	Thyborøn, Denmark	Fire	Analyses, advice, and restoration
Container ship	2007	Grenaa, Denmark	Salt water	Advice
Ro/Ro	2007	Harstad, Norway	Fire	Analyses, advice, and restoration
Container ship	2007	Odense, Denmark	Fire	Analyses and advice
Trawler	2007	Frederikshavn, Denmark	Fire	Analyses and advice
Ferry	2007	Hirtshals, Denmark	Salt water	Analyses, advice, and restoration
Platform	2007	The North Sea	Fire	Analyses, advice, and restoration
Platform	2007	Singapore	Fire	Analyses and advice
Fishery protection vessel	2007	Tórshavn, Faroe Islands	Fire	Analyses, advice, and restoration
Standby/Rescue	2007	Esbjerg, Denmark	Fire	Analyses and advice
Carrier	2007	Esbjerg, Denmark	Fire	Analyses, advice, and restoration
Trawler	2007	Thyborøn, Denmark	Salt water	Analyses, advice, and restoration
Chemical tanker	2007	Shanghai, China	Fire	Analyses, advice, and restoration
Container ship	2007	Lisbon, Portugal	Fire	Analyses and advice
Inspection vessel	2007	Skagen, Denmark	Fire	Analyses and advice
Bulk carrier	2006	Fredericia, Denmark	Salt water	Cleaning



Type	Year	Location	Damage	AREPA's effort
Trawler	2006	The Faroe Islands	Fire	Analyses and advice
Supply vessel	2006	Esbjerg, Denmark	Fire	Analyses and advice
Fishing vessel	2006	Thyborøn, Denmark	Fire	Analyses and advice
Supply vessel	2006	Sokhna, Egypt	Fire	Analyses, advice, and restoration
Fishing vessel	2006	Thyborøn, Denmark	Fire	Analyses, advice, and restoration
Container ship	2006	Barcelona, Spain	Fire	Analyses and advice
Survey ship	2006	Silkeborg, Denmark	Water	Restoration
Fishing vessel	2006	Gdynia, Poland	Fire	Analyses, consultancy, and supervision of restoration by others
Container ship	2006	Odense, Denmark	Fire and salt water	Analyses, advice, and restoration
Trawler	2006	Hirtshals and Frederikshavn, Denmark	Fire	Analyses and advice
Tanker	2006	La Coruna, Spain + Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Supply vessel	2006	Esbjerg, Denmark	Fire	Analyses, advice, and restoration
Trawler	2006	Runavik, Faroe Islands	Fire	Analyses, advice, and restoration
Tanker	2006	Vlaardingen, Holland	Fire	Analyses, advice, restoration, and supervision
Refrigerator ship	2006	Durban, South Africa	Fire	Analyses and advice
Tug boat	2006	Fredericia, Denmark	Fire	Analyses, advice, and restoration
Components from a Bayliner 205	2006	Silkeborg, Denmark	Salt water	Advice
Trawler	2006	Hirtshals, Denmark	Fire	Analyses and advice
Bulk carrier	2005	Riga, Latvia	Fire	Analyses and advice
Tanker	2005	Køge and Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Naval vessel	2005	Frederikshavn, Denmark	Fire	Analyses and advice
Side-loading pallet carrier	2005	Tilbury, England	Fire	Analyses and advice
Car carrier	2005	Piraeus, Greece	Fire	Analyses, advice, and restoration
Platform	2005	Offshore	Dust	3 x restoration
Trawler	2005	Runavik, The Faroe Islands	Fire	Analyses and advice
Standby/Rescue vessel	2005	Esbjerg, Denmark	Fire	Analyses, advice, and restoration
Ferry	2005	Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Tanker	2005	Dubai, United Arab Emirates	Fire	Analyses, advice, and restoration
Platform	2005	Offshore	Salt water	Advice and restoration
Ferry	2005	Geoje, Korea	Fire	Analyses and advice
Container ship	2005	Cadiz, Spain	Fire	Analyses, advice, and restoration
Diving ship	2005	Grenaa, Denmark	Fire	Analyses and advice
Roll-on/roll-off ship	2005	Dubai, United Arab Emirates	Fire	Analyses and advice
Platform ship	2005	Frederikshavn, Denmark	Maintenance	Cleaning



Type	Year	Location	Damage	AREPA's effort
Supply vessel	2004/2005	Halifax, Canada	Water, fire and powder	Analyses, advice, and restoration
Chemical tanker	2004	Port Torres, Sardinia	Explosion	Data reconstruction, analyses, and advice
Cruise ship	2004	Bremerhaven, Germany	Water	Advice
Bulk carrier	2004	Stavanger, Norway	Water	Advice
Fishing-vessel	2004	Esbjerg, Denmark	Fire	Analyses, advice, and restoration
Fishing-vessel	2004	Esbjerg, Denmark	Fire	Analyses and advice
Sailing boat	2004	Struer, Denmark	Fire	Analyses, advice, and restoration
Fishing-vessel	2004	Grenaa, Denmark	Fire	Analyses and advice
Tanker	2004	Fredericia, Denmark	Fire	Analyses, advice, and restoration
Tanker	2004	Jeddah	Water	Advice and restoration
Standby/rescue vessel	2004	Frederikshavn, Denmark	Fire	Analyses and advice
Trawler	2004	Esbjerg, Denmark	Fire	Analyses and advice
Dredger	2004	Esbjerg, Denmark	Water	Advice and restoration
Fishing-vessel	2004	Esbjerg, Denmark	Fire	Analyses and advice
Supply vessel	2004	Esbjerg, Denmark	Fire	Analyses, advice, and restoration
Buoy	2003	Offshore	Oil/soot	Advice and restoration
Supply boat	2003	Singapore	Water	Advice and restoration
	2003	Norway	Fire	Restoration
Fishing-vessel	2003	Aabenraa, Denmark	Fire	Analyses, advice, and restoration
Fishing-vessel	2003	Juelsminde, Denmark	Fire	Analyses, advice, and restoration
Liner	2003	Iceland	Water	Advice
Supply boat	2003	Esbjerg, Denmark	Fire	Restoration
Ferry	2003	Rostock, Germany	Fire	Analyses and advice
Coaster	2003	Yemen, Constanta and Istanbul	Fire	Analyses, advice, and restoration
Ferry	2003	Ystad, Sweden	Fire	Analyses and advice
Tanker	2003	Fredericia, Denmark	Fire	Analyses and advice
Refrigerator ship	2003	Aarhus, Denmark	Fire	Analyses, advice, and restoration
Ferry	2003	Esbjerg, Denmark	Water	Advice
	2003	Esbjerg, Denmark		Advice
Ferry	2002	Rønne, Denmark	Fire	Analyses and advice
	2002	Norway	Water	Restoration
Ro/Ro	2002	Bremerhaven, Germany	Fire	Analyses, advice, and restoration
Tanker	2002	Algeciras, Spain	Fire	Analyses, advice, and restoration
	2002	England	Fire	Analyses
	2002	West India	Water	Restoration

Type	Year	Location	Damage	AREPA's effort
Cargo ship	2002	Taranto, Italy	Fire	Analyses, advice, and restoration
Ferry	2002	Kristianssand, Norway	Fire	Analyses and advice
Fishing-vessel	2002	Hanstholm, Denmark	Fire	Analyses and advice
Ro/Ro	2002	Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Tanker	2002	Salvadore, Brazil	Fire	Analyses and advice
Ro/Ro	2002	Scotland	Water	Advice and restoration
Rebuilt pilot boat	2002	Esbjerg, Denmark	Fire	Analyses and advice
Cruise ship	2002	Thyborøn, Denmark	Fire	Analyses, advice, and restoration
Supply boat	2002	Stralsund, Germany	Fire	Analyses and advice
	2002	Spain/Africa	Water	Restoration
Tanker	2001	Le Havre, France	Fire	Analyses, advice, and restoration
Cruise ship	2001	Aalborg, Denmark	Fire	Analyses and advice
Cargo vessel	2001	Panama, Equador	Water	Advice and restoration
Tanker	2001	Le Havre, France	Fire	Analyses after fire in engine room
Supply boat	2001	Ølen, Norway	Fire	Analyses after fire in engine room
Ferry	2001	Sassnits, Deutschland	Fire	Analyses, advice, and restoration
Tanker	2001	Nantong, China	Fire	Analyses and advice
Tanker	2001	Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Subsea cable ship	2001	Esbjerg, Denmark	Fire	Analyses, advice, and restoration
Tanker	2001	Rilica, Croatia	Fire	Analyses after fire in engine room
Tanker	2001	Piraeus, Greece	Water	Analyses and advice
Trawler	2001	Hvide Sande, Denmark	Water	Advice and restoration
Tanker	2001	Suez, Egypt	Fire	Analyses and advice
	2001	Norway	Water	Restoration
Gas prod. platform	2000	The North Sea	Dust	Restoration
Ferry	2000	Frederikshavn, Denmark	Fire	Analyses and advice
Floating oil drilling rig	2000	Belfast, Ireland	Water	Analyses and advice
Gas prod. platform	2000	Stavanger, Norway	Fire	Analyses
Fishing vessel	2000	Thyborøn, Denmark	Fire	Analyses and advice
Fishing vessel	2000	Skagen, Denmark	Fire	Analyses, advice, and restoration
Trawler	2000	Esbjerg, Denmark	Fire	Analyses, advice, and restoration
Standby/rescue vessel	2000	Esbjerg, Denmark	Fire	Analyses, advice, and restoration
Research vessel	2000	Oresund, Sweden	Fire	Advice and co-ordination
Ferry	2000	Stord, Norway	Water	Reconstruction of data after 4 months on the seabed
Product carrier	2000	Singapore	Fire	Analyses, advice, and restoration

Type	Year	Location	Damage	AREPA's effort
Container vessel	2000	Kobe, Japan	Fire	Analyses, advice, and restoration after explosion
Supply boat	2000	Rio de Janeiro, Brazil	Fire	Analyses, advice, restoration, and co-ordination
	2000	Norway	Fire	Analyses
Submarine	2000	Frederikshavn + Aarhus, Denmark	Fire	Analyses and advice
Ferry	2000	Narsaq, Greenland	Fire	Analyses, advice, and restoration
Supply boat	2000	Trinidad	Fire	Analyses, advice, and restoration
	2000	Norway	Fire	Restoration
Gas prod. vessel	2000	Point Noire, Congo	Fire	Analyses, advice, and restoration
	2000	Norway	Fire	Restoration
Ferry	2000	Ærø, Denmark	Fire	Analyses, advice, and restoration
Oil rig	2000	Cadiz, Spain	Dust	Restoration after dust contamination on electronics
Ro/Ro	2000	Gothenburg, Sweden	Fire	Analyses and restoration
	2000	Norway	Fire	Restoration
Fishing trawler	1999	Egersund, Norway	Fire	Restoration
Gas prod. platform	1999	Haugesund, Norway	Fire	Analyses and restoration
Cargo boat	1999	Arendal, Norway	Fire	Restoration
Trawler	1999	Stavanger, Norway	Fire	Analyses
Container vessel	1999	Odense, Denmark	Fire	Analyses and advice
Yacht	1999	Genua, Italy	Fire	Analyses, advice, and restoration
Supply boat	1999	Point Noire, Congo	Fire	Analyses, advice, and restoration
Rig	1999	The North Sea	Fire	Analyses, advice, restoration, and co-ordination
Supply boat	1999	Eggesund, Norway		
Ro/Ro	1999	Gothenburg, Sweden	Water	Analyses, advice, and co-ordination
Ferry	1999	Trelleborg, Sweden	Fire	Analyses, advice, and restoration of switchboards
Ro/Ro	1999	Gothenburg, Sweden	Water	Advice and supervision
Trawler	1999	Thyborøn, Denmark	Fire	Analyses, advice, and restoration
Protection vessel	1999	Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Ferry	1999	Fredericia, Denmark	Oil pollution	Advice and restoration
Crane	1999	Esbjerg, Denmark	Water	Advice and co-ordination
Gas prod. platform	1999	Stavanger, Norway	Dust	Restoration of electronics
Gas prod. platform	1999	The North Sea	Dust	Analyses
Cruise ship	1999	Gothenburg, Sweden		



Type	Year	Location	Damage	AREPA's effort
Subsea cable ship	1999	Ålesund, Norway	Dust	Analyses and restoration
Factory ship	1999	Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Trawler	1999	Skagen, Denmark	Water	Advice and restoration
Gas prod. platform	1999	The North Sea	Smoke	Analyses
Oil drilling rig	1999	Esbjerg, Denmark	Salt pollution	Restoration
Container vessel	1999	Odense, Denmark	Fire	Analyses and advice
	1998	Gothenburg, Sweden		
Tanker	1998	Copenhagen + Marstal, Denmark	Fire	Analyses, advice, and restoration
Dredger	1998	Thyborøn, Denmark	Fire	Analyses, advice, and restoration
Trawler	1998	Skagen, Denmark	Fire	Analyses, advice, and restoration
Lifeboat	1998	Aalborg, Denmark	Water	Analyses, advice, and restoration
Fishing vessel	1998	Thyborøn, Denmark	Fire	Analyses, advice, and restoration
Ferry	1998	Fredericia, Denmark	Fire	Analyses, advice, and restoration
Tanker	1998	Tjøemme, Norway	Fire	Restoration
Tanker	1998	Fredericia, Denmark	Fire	Analyses and advice
Container vessel	1998	Falmouth, Cornwall, UK	Fire	Analyses, advice, restoration, and co-ordination
Ferry	1998	Marseille + Bastia, France	Fire	Analyses, advice, restoration, and co-ordination
	1998	Aarhus, Denmark	Water	Advice and restoration
Dredger	1998	Aarhus, Denmark	Water	Analyses, advice, and restoration
	1998	Floroe, Norway	Dust	Analyses, advice, and restoration
Hotel rig	1998	Haugesund, Norway	Fire	Analyses and restoration of electrical switch-gears
Trawler	1998	Hirtshals, Denmark	Fire	Analyses and restoration
Oil prod. ship	1998	The North Sea	Water	Restoration
	1997	Rotterdam, Netherlands		
Trawler	1997	Bremen, Germany		
Supply vessel	1997	Fredericia, Denmark	Fire	Analyses and advice
Tug boat	1997	Fredericia, Denmark	Fire	Analyses and advice
Tanker	1997	Frederikshavn, Denmark	Fire	Analyses, advice, and restoration
Seismic vessel	1997	Aarhus, Denmark	Oil pollution	Analyses and advice
Container vessel	1997	Odense, Denmark	Fire	Analyses, advice, and restoration
Gas tanker	1997	The Gulf, United Arab Emirates	Fire	Analyses, advice, restoration, and co-ordination
Platform	1997	Esbjerg, Denmark	Water	Restoration
Environmental boat	1997	Randers, Denmark	Water	Advice and restoration

Type	Year	Location	Damage	AREPA's effort
Chemical tanker	1997	Rotterdam, Netherlands	Fire	Analyses, advice, restoration, and co-ordination
Supply vessel	1997	Grimstad, Norway	Fire	Analyses, advice, and restoration
Cruise liner	1997	Bremen, Germany	Fire	Analyses and advice
Research vessel	1997	Stavanger, Norway	Fire	Restoration
Tug Vessel	1997	Great Belt, Denmark	Water	Analyses and restoration of communication equipment
Cruise ship	1997	Southampton, UK	Fire	Analyses, advice, restoration, and co-ordination
	1997	Norway	Water	Recovery of data
Ferry	1996	Marseille, France		
Trawler	1996	Aalborg, Denmark		
	1996	Aalborg, Denmark		
Trawler	1996	Esbjerg, Denmark		
Research vessel	1996	Aarhus, Denmark		
Trawler	1996	Frederikshavn, Denmark		
Ro/Ro	1996	Fredericia, Denmark		
Platform	1996	Gorm Field, North Sea		
Ferry	1996	Esbjerg, Denmark		
Trawler	1995	Amsterdam, Netherlands		
Ferry	1995	Esbjerg, Denmark		
Fishing ship	1995	Pusan, Korea		
Freeze ship	1995	Rotterdam, Netherlands		
Platform	1995	The North Sea		
Container ship	1995	Rotterdam, Netherlands, and Esbjerg, Denmark		
Oil rig	1995	Stavanger, Norway		
Ferry	1995	Copenhagen, Denmark		
Diving supply ship	1995	Aarhus, Denmark		
Supply boat	1995	Rotterdam, Netherlands		
Trawler	1994	Christchurch, New Zealand		
Coast streamer	1994	Volda		
Trawler	1994	Iceland		
Bulk carrier	1994	Riga		
Platform	1994	The North Sea		
Corvette	1994	Korsør, Denmark		
Ferry	1994	Hundested, Denmark		



Type	Year	Location	Damage	AREPA's effort
Trawler	1993	Norway		
Freeze ship	1993	Las Palmas		
Cable streamer	1993	Krisland, Norway		
Ferry	1993	Esbjerg, Denmark		
Supply vessel	1993	Aberdeen, Scotland, and Fredericia, Denmark		
Trawler	1993	The Faroe Islands		
Container ship	1993	Gothenburg, Sweden		
Research vessel	1992	Horten, Norway		
Tug boat	1992	Langøya, Norway		
Trawler	1992	Greenland		
Bulk carrier	1991	Gothenburg, Sweden		
Barge	1986	Sharjar, United Arab Emirates		
Container ship	1985	Rotterdam, Netherlands		